PATE	0228Z 06 DEC 60 P 5 E C REL					
TO	DIRECTOR 25X1A	OPERATIONAL IMMEDIATE OPERATIONAL IMMEDIATE				
ACTION	OPS (1,2,3,4)					
an po	: S/C (5) DHD	IN 38495				
er (d nemocratical) (september 2) 2 yr - Hart Strick (september 2) 20 (september 2)	TOR: 0340Z OS DEC SO					
25X1A	GREEN EYES	045 25X1				
20/(1/(* COCO & 1070 A				
	1. REF SORTIE 3011 ARTICLE ARRIVED POINT COCOA 1238Z AT BASE PLUS 18.7 WITH NO CONTRAILS PRESENT. ARRIVED POINT DELTA					
	1250Z AT BASE PLUS 13.4 WITH NO CONTRAILS PRESENT. ARRIVED					
	POINT APPROXIMATELY 32 MILES ON TRACK BEYOND DELTA 23;07					
	NORTH 8128 WEST AT BASE PLUS 18.8 AND DXPERIENCED HEAVY					
	INTERMITTENT CONTRAILS. MADE TURN TO NORTH CLIMBING TO MAX					
	ALTITUDE OF 190 AND CONTRAILS PERSISTED. AIR ABORTED AND RETURNED ON TRACK AFTER CLEAR OF LAND MASS OF CUBA.					
	2. ENTIRE LAND MASS OF AREA OF INTEREST CAT 5 EXCEPT FOR PINOS					
	ISLAND AS FAR AS PILOT COULD SEE VISUALLY FR					
25X1A						
	SECURITY 4080TH SW WING HAVE LANDED THERE NU					
	BASE PERSONNEL ASSUMED THIS ARTICLE TO BELONG TO 4080TH.					
	DRIVER WAS NOT QUESTIONED BY ANYONE RELATIVE TO THE MISSION					
25X1A	AND SINCE THE WEATHER AT WAS KNOWN TO BE					
Decu	WAS ACCEPTED AS COMPLETELY ROUTINE. DRIVER F					
clas Clas Next Adih	Approximent Approximent OTHER THAN THE ISSUING OFFICE	00569R000300030020-4 IS PROHIBITED. Copy No.				

	Approve	d For Release 2	002/08/21 🛮 🗗	FDP age 03-99	R00030020-4
PAGE : 25X1A	2, 045,	IN 38495	TORS	ECRET	

COOPERATION AND WAS PROVIDED WITH A MILITARY GUARD FOR SECURITY OF THE AIRCRAFT.

4. IT IS POSSIBLE THAT ARTICLE 342 HAS SOME WIRING OR ELECTRICAL DEFICIENCY THAT HAS NOT YET BEEN PINPOINTED. RADIO FAILURE HAS BEEN EXPERIENCED ON PREVIOUS FLIGHTS. AFTER THE SET IS CHANGED IT OPERATES SATISFACTORILY FOR ONE OR TWO FLIGHTS AND REOCCURS AGAIN. TROUBLE SHOOTING IS IN PROGRESS IN AN EFFORT TO DETERMINE THE EXACT CAUSE.

END OF MESSAGE